
APPENDIX A

ENGINEERING APPENDIX FIGURES 51-100

Jacksonville Harbor Navigation Study, Duval County, Florida

DRAFT
INTEGRATED GENERAL REEVALUATION
REPORT II AND SUPPLEMENTAL
ENVIRONMENTAL IMPACT STATEMENT



JACKSONVILLE DISTRICT, CORPS OF ENGINEERS
JACKSONVILLE, FLORIDA


CHECKED BY: DATED:

MARCH 2013

CUT-5 STATION 5+00 TO 7+00 GENERAL REEVALUATION REPORT II - ENGINEERING APPENDIX NOTE: SHORELINE FALLS OUTSIDE LIMITS OF

SECTION ON SECTIONS WHERE APPROXIMATE

SHORELINE SYMBOL IS NOT SHOWN.




JACKSONVILLE DISTRICT, CORPS OF ENGINEERS
JACKSONVILLE, FLORIDA

CHECKED BY: DATED: **MARCH 2013**

DREDGING CROSS SECTIONS CUT-5 STATION 8+00 TO 10+00 GENERAL REEVALUATION REPORT II - ENGINEERING APPENDIX

NOTE: SHORELINE FALLS OUTSIDE LIMITS OF SECTION ON SECTIONS WHERE APPROXIMATE

SHORELINE SYMBOL IS NOT SHOWN.



JACKSONVILLE DISTRICT, CORPS OF ENGINEERS
JACKSONVILLE, FLORIDA


CHECKED BY: DATED:

MARCH 2013

CUT-5 STATION 11+00 TO 13+00 GENERAL REEVALUATION REPORT II - ENGINEERING APPENDIX NOTE: SHORELINE FALLS OUTSIDE LIMITS OF

SECTION ON SECTIONS WHERE APPROXIMATE

SHORELINE SYMBOL IS NOT SHOWN.



JACKSONVILLE DISTRICT, CORPS OF ENGINEERS
JACKSONVILLE, FLORIDA


CHECKED BY: DATED:

MARCH 2013

CUT-6 STATION 1+00 TO 3+00 GENERAL REEVALUATION REPORT II - ENGINEERING APPENDIX NOTE: SHORELINE FALLS OUTSIDE LIMITS OF

SECTION ON SECTIONS WHERE APPROXIMATE

SHORELINE SYMBOL IS NOT SHOWN.





JACKSONVILLE DISTRICT, CORPS OF ENGINEERS
JACKSONVILLE, FLORIDA


CHECKED BY: DATED: **MARCH 2013**

CUT-6 STATION 4+00 TO 6+00 GENERAL REEVALUATION REPORT II - ENGINEERING APPENDIX

NOTE: SHORELINE FALLS OUTSIDE LIMITS OF

SECTION ON SECTIONS WHERE APPROXIMATE

SHORELINE SYMBOL IS NOT SHOWN.



JACKSONVILLE DISTRICT, CORPS OF ENGINEERS
JACKSONVILLE, FLORIDA


CHECKED BY: DATED:

MARCH 2013

DREDGING CROSS SECTIONS CUT-6 STATION 7+00 TO 9+00 GENERAL REEVALUATION REPORT II - ENGINEERING APPENDIX NOTE: SHORELINE FALLS OUTSIDE LIMITS OF

SECTION ON SECTIONS WHERE APPROXIMATE

SHORELINE SYMBOL IS NOT SHOWN.




JACKSONVILLE DISTRICT, CORPS OF ENGINEERS
JACKSONVILLE, FLORIDA

CHECKED BY: DATED:

MARCH 2013

CUT-6 STATION 10+00 TO 12+00 GENERAL REEVALUATION REPORT II - ENGINEERING APPENDIX NOTE: SHORELINE FALLS OUTSIDE LIMITS OF SECTION ON SECTIONS WHERE APPROXIMATE

SHORELINE SYMBOL IS NOT SHOWN.



JACKSONVILLE DISTRICT, CORPS OF ENGINEERS
JACKSONVILLE, FLORIDA


CHECKED BY: DATED:

MARCH 2013

CUT-6 STATION 13+00 TO 15+00 GENERAL REEVALUATION REPORT II - ENGINEERING APPENDIX NOTE: SHORELINE FALLS OUTSIDE LIMITS OF

SECTION ON SECTIONS WHERE APPROXIMATE

SHORELINE SYMBOL IS NOT SHOWN.






JACKSONVILLE DISTRICT, CORPS OF ENGINEERS
JACKSONVILLE, FLORIDA

CHECKED BY: DATED: **MARCH 2013**

CUT-6 STATION 16+00 TO 18+00 GENERAL REEVALUATION REPORT II - ENGINEERING APPENDIX NOTE: SHORELINE FALLS OUTSIDE LIMITS OF

SECTION ON SECTIONS WHERE APPROXIMATE

SHORELINE SYMBOL IS NOT SHOWN.



JACKSONVILLE DISTRICT, CORPS OF ENGINEERS
JACKSONVILLE, FLORIDA


CHECKED BY: DATED:

MARCH 2013

CUT-6 STATION 19+00 TO 21+00 GENERAL REEVALUATION REPORT II - ENGINEERING APPENDIX NOTE: SHORELINE FALLS OUTSIDE LIMITS OF

SECTION ON SECTIONS WHERE APPROXIMATE

SHORELINE SYMBOL IS NOT SHOWN.






JACKSONVILLE DISTRICT, CORPS OF ENGINEERS
JACKSONVILLE, FLORIDA

CHECKED BY: DATED:

MARCH 2013

DREDGING CROSS SECTIONS CUT-6 STATION 22+00 TO CUT-7 2+00 GENERAL REEVALUATION REPORT II - ENGINEERING APPENDIX

NOTE: SHORELINE FALLS OUTSIDE LIMITS OF SECTION ON SECTIONS WHERE APPROXIMATE SHORELINE SYMBOL IS NOT SHOWN.





JACKSONVILLE DISTRICT, CORPS OF ENGINEERS
JACKSONVILLE, FLORIDA


CHECKED BY: DATED: **MARCH 2013**

DREDGING CROSS SECTIONS CUT-7 STATION 3+00 TO 5+00 GENERAL REEVALUATION REPORT II - ENGINEERING APPENDIX

NOTE: SHORELINE FALLS OUTSIDE LIMITS OF

SECTION ON SECTIONS WHERE APPROXIMATE

SHORELINE SYMBOL IS NOT SHOWN.



JACKSONVILLE DISTRICT, CORPS OF ENGINEERS
JACKSONVILLE, FLORIDA


CHECKED BY: DATED: **MARCH 2013**

CUT-7 STATION 6+00 TO 8+00 GENERAL REEVALUATION REPORT II - ENGINEERING APPENDIX

NOTE: SHORELINE FALLS OUTSIDE LIMITS OF

SECTION ON SECTIONS WHERE APPROXIMATE

SHORELINE SYMBOL IS NOT SHOWN.



JACKSONVILLE DISTRICT, CORPS OF ENGINEERS
JACKSONVILLE, FLORIDA


CHECKED BY: DATED:

MARCH 2013

DREDGING CROSS SECTIONS CUT-7 STATION 9+00 TO 11+00 GENERAL REEVALUATION REPORT II - ENGINEERING APPENDIX NOTE: SHORELINE FALLS OUTSIDE LIMITS OF

SECTION ON SECTIONS WHERE APPROXIMATE

SHORELINE SYMBOL IS NOT SHOWN.



JACKSONVILLE DISTRICT, CORPS OF ENGINEERS
JACKSONVILLE, FLORIDA


CHECKED BY: DATED:

MARCH 2013

CUT-7 STATION 12+00 TO 14+00 GENERAL REEVALUATION REPORT II - ENGINEERING APPENDIX NOTE: SHORELINE FALLS OUTSIDE LIMITS OF

SECTION ON SECTIONS WHERE APPROXIMATE

SHORELINE SYMBOL IS NOT SHOWN.




JACKSONVILLE DISTRICT, CORPS OF ENGINEERS
JACKSONVILLE, FLORIDA

CHECKED BY: DATED: **MARCH 2013**

CUT-7 STATION 15+00 TO 17+00 GENERAL REEVALUATION REPORT II - ENGINEERING APPENDIX NOTE: SHORELINE FALLS OUTSIDE LIMITS OF

SECTION ON SECTIONS WHERE APPROXIMATE

SHORELINE SYMBOL IS NOT SHOWN.




JACKSONVILLE DISTRICT, CORPS OF ENGINEERS
JACKSONVILLE, FLORIDA

CHECKED BY: DATED: **MARCH 2013**

CUT-7 STATION 18+00 TO 20+00 GENERAL REEVALUATION REPORT II - ENGINEERING APPENDIX NOTE: SHORELINE FALLS OUTSIDE LIMITS OF

SECTION ON SECTIONS WHERE APPROXIMATE

SHORELINE SYMBOL IS NOT SHOWN.




JACKSONVILLE DISTRICT, CORPS OF ENGINEERS
JACKSONVILLE, FLORIDA

CHECKED BY: DATED:

MARCH 2013

CUT-7 STATION 21+00 TO 23+00 GENERAL REEVALUATION REPORT II - ENGINEERING APPENDIX NOTE: SHORELINE FALLS OUTSIDE LIMITS OF SECTION ON SECTIONS WHERE APPROXIMATE

SHORELINE SYMBOL IS NOT SHOWN.



JACKSONVILLE DISTRICT, CORPS OF ENGINEERS
JACKSONVILLE, FLORIDA


CHECKED BY: DATED:

MARCH 2013

CUT-7 STATION 24+00 TO 26+00 GENERAL REEVALUATION REPORT II - ENGINEERING APPENDIX NOTE: SHORELINE FALLS OUTSIDE LIMITS OF

SECTION ON SECTIONS WHERE APPROXIMATE

SHORELINE SYMBOL IS NOT SHOWN.



JACKSONVILLE DISTRICT, CORPS OF ENGINEERS
JACKSONVILLE, FLORIDA


CHECKED BY: DATED:

MARCH 2013

CUT-7 STATION 27+00 TO CUT-8 STATION 1+00 GENERAL REEVALUATION REPORT II - ENGINEERING APPENDIX NOTE: SHORELINE FALLS OUTSIDE LIMITS OF

SECTION ON SECTIONS WHERE APPROXIMATE


SHORELINE SYMBOL IS NOT SHOWN.



JACKSONVILLE DISTRICT, CORPS OF ENGINEERS
JACKSONVILLE, FLORIDA

CHECKED BY: DATED: **MARCH 2013**

DREDGING CROSS SECTIONS CUT-8 STATION 2+00 TO 4+00 GENERAL REEVALUATION REPORT II - ENGINEERING APPENDIX NOTE: SHORELINE FALLS OUTSIDE LIMITS OF SECTION ON SECTIONS WHERE APPROXIMATE




JACKSONVILLE DISTRICT, CORPS OF ENGINEERS
JACKSONVILLE, FLORIDA

DATED:

MARCH 2013

CUT-8 STATION 5+00 TO 7+00 GENERAL REEVALUATION REPORT II - ENGINEERING APPENDIX

NOTE: SHORELINE FALLS OUTSIDE LIMITS OF SECTION ON SECTIONS WHERE APPROXIMATE




JACKSONVILLE DISTRICT, CORPS OF ENGINEERS
JACKSONVILLE, FLORIDA

DATED:

MARCH 2013

CUT-8 STATION 8+00 TO 10+00 GENERAL REEVALUATION REPORT II - ENGINEERING APPENDIX NOTE: SHORELINE FALLS OUTSIDE LIMITS OF SECTION ON SECTIONS WHERE APPROXIMATE

SHORELINE SYMBOL IS NOT SHOWN.




JACKSONVILLE, FLORIDA

CHECKED BY: DATED:

MARCH 2013

CUT-8 STATION 11+00 TO 13+00 GENERAL REEVALUATION REPORT II - ENGINEERING APPENDIX NOTE: SHORELINE FALLS OUTSIDE LIMITS OF SECTION ON SECTIONS WHERE APPROXIMATE

SHORELINE SYMBOL IS NOT SHOWN.




JACKSONVILLE DISTRICT, CORPS OF ENGINEERS
JACKSONVILLE, FLORIDA

CHECKED BY: DATED:

MARCH 2013

CUT-8 STATION 14+00 TO 16+00 GENERAL REEVALUATION REPORT II - ENGINEERING APPENDIX NOTE: SHORELINE FALLS OUTSIDE LIMITS OF SECTION ON SECTIONS WHERE APPROXIMATE

SHORELINE SYMBOL IS NOT SHOWN.




JACKSONVILLE DISTRICT, CORPS OF ENGINEERS
JACKSONVILLE, FLORIDA

CHECKED BY: DATED:

MARCH 2013

CUT-8 STATION 17+00 TO 19+00 GENERAL REEVALUATION REPORT II - ENGINEERING APPENDIX NOTE: SHORELINE FALLS OUTSIDE LIMITS OF SECTION ON SECTIONS WHERE APPROXIMATE

SHORELINE SYMBOL IS NOT SHOWN.



JACKSONVILLE DISTRICT, CORPS OF ENGINEERS
JACKSONVILLE, FLORIDA


CHECKED BY: DATED:

MARCH 2013

CUT-8 STATION 20+00 TO 22+00 GENERAL REEVALUATION REPORT II - ENGINEERING APPENDIX

NOTE: SHORELINE FALLS OUTSIDE LIMITS OF SECTION ON SECTIONS WHERE APPROXIMATE

SHORELINE SYMBOL IS NOT SHOWN.




JACKSONVILLE DISTRICT, CORPS OF ENGINEERS
JACKSONVILLE, FLORIDA

DATED:

MARCH 2013

CUT-8 STATION 23+00 TO CUT-9 STATION 1+00 GENERAL REEVALUATION REPORT II - ENGINEERING APPENDIX NOTE: SHORELINE FALLS OUTSIDE LIMITS OF SECTION ON SECTIONS WHERE APPROXIMATE




JACKSONVILLE DISTRICT, CORPS OF ENGINEERS
JACKSONVILLE, FLORIDA

DATED:

MARCH 2013


CUT-9 STATION 2+00 TO 4+00 GENERAL REEVALUATION REPORT II - ENGINEERING APPENDIX SECTION ON SECTIONS WHERE APPROXIMATE



DATED:

MARCH 2013

CUT-9 STATION 5+00 TO 7+00 GENERAL REEVALUATION REPORT II - ENGINEERING APPENDIX



JACKSONVILLE DISTRICT, CORPS OF ENGINEERS
JACKSONVILLE, FLORIDA


CHECKED BY: DATED:

MARCH 2013

CUT-9 STATION 8+00 TO 10+00 GENERAL REEVALUATION REPORT II - ENGINEERING APPENDIX NOTE: SHORELINE FALLS OUTSIDE LIMITS OF

SECTION ON SECTIONS WHERE APPROXIMATE

SHORELINE SYMBOL IS NOT SHOWN.




JACKSONVILLE DISTRICT, CORPS OF ENGINEERS
JACKSONVILLE, FLORIDA

CHECKED BY: DATED:

MARCH 2013

CUT-9 STATION 11+00 TO 13+00 GENERAL REEVALUATION REPORT II - ENGINEERING APPENDIX NOTE: SHORELINE FALLS OUTSIDE LIMITS OF SECTION ON SECTIONS WHERE APPROXIMATE

SHORELINE SYMBOL IS NOT SHOWN.




JACKSONVILLE DISTRICT, CORPS OF ENGINEERS
JACKSONVILLE, FLORIDA

DATED:

MARCH 2013

CUT-9 STATION 14+00 TO 16+00 GENERAL REEVALUATION REPORT II - ENGINEERING APPENDIX SECTION ON SECTIONS WHERE APPROXIMATE




JACKSONVILLE DISTRICT, CORPS OF ENGINEERS
JACKSONVILLE, FLORIDA

CHECKED BY: DATED:

MARCH 2013

CUT-9 STATION 17+00 TO 19+00 GENERAL REEVALUATION REPORT II - ENGINEERING APPENDIX

NOTE: SHORELINE FALLS OUTSIDE LIMITS OF SECTION ON SECTIONS WHERE APPROXIMATE SHORELINE SYMBOL IS NOT SHOWN.




JACKSONVILLE DISTRICT, CORPS OF ENGINEERS
JACKSONVILLE, FLORIDA

DATED:

MARCH 2013

CUT-9 STATION 20+00 TO 22+00 GENERAL REEVALUATION REPORT II - ENGINEERING APPENDIX

SECTION ON SECTIONS WHERE APPROXIMATE



JACKSONVILLE DISTRICT, CORPS OF ENGINEERS
JACKSONVILLE, FLORIDA


DATED:

MARCH 2013

CUT-9 STATION 23+00 TO CUT-10 STATION 1+00 GENERAL REEVALUATION REPORT II - ENGINEERING APPENDIX

NOTE: SHORELINE FALLS OUTSIDE LIMITS OF

SECTION ON SECTIONS WHERE APPROXIMATE




JACKSONVILLE DISTRICT, CORPS OF ENGINEERS
JACKSONVILLE, FLORIDA

CHECKED BY: DATED:

MARCH 2013

CUT-10 STATION 2+00 TO 4+00 GENERAL REEVALUATION REPORT II - ENGINEERING APPENDIX NOTE: SHORELINE FALLS OUTSIDE LIMITS OF SECTION ON SECTIONS WHERE APPROXIMATE

SHORELINE SYMBOL IS NOT SHOWN.






JACKSONVILLE DISTRICT, CORPS OF ENGINEERS
JACKSONVILLE, FLORIDA

DATED: **MARCH 2013**

CUT-10 STATION 5+00 TO 7+00 GENERAL REEVALUATION REPORT II - ENGINEERING APPENDIX NOTE: SHORELINE FALLS OUTSIDE LIMITS OF SECTION ON SECTIONS WHERE APPROXIMATE




JACKSONVILLE DISTRICT, CORPS OF ENGINEERS
JACKSONVILLE, FLORIDA

DATED:

MARCH 2013

CUT-11 STATION 1+00 TO 3+00 GENERAL REEVALUATION REPORT II - ENGINEERING APPENDIX NOTE: SHORELINE FALLS OUTSIDE LIMITS OF SECTION ON SECTIONS WHERE APPROXIMATE

SHORELINE SYMBOL IS NOT SHOWN.




JACKSONVILLE DISTRICT, CORPS OF ENGINEERS
JACKSONVILLE, FLORIDA

DATED:

MARCH 2013

CUT-11 STATION 4+00 TO 6+00 GENERAL REEVALUATION REPORT II - ENGINEERING APPENDIX

SECTION ON SECTIONS WHERE APPROXIMATE




JACKSONVILLE DISTRICT, CORPS OF ENGINEERS
JACKSONVILLE, FLORIDA

CHECKED BY: DATED:

MARCH 2013

DREDGING CROSS SECTIONS CUT-12 STATION 1+00 TO 3+00 GENERAL REEVALUATION REPORT II - ENGINEERING APPENDIX NOTE: SHORELINE FALLS OUTSIDE LIMITS OF SECTION ON SECTIONS WHERE APPROXIMATE

SHORELINE SYMBOL IS NOT SHOWN.



JACKSONVILLE, FLORIDA


CHECKED BY: DATED:

MARCH 2013

CUT-12 STATION 4+00 TO CUT-13 STATION 2+00 GENERAL REEVALUATION REPORT II - ENGINEERING APPENDIX

NOTE: SHORELINE FALLS OUTSIDE LIMITS OF SECTION ON SECTIONS WHERE APPROXIMATE

SHORELINE SYMBOL IS NOT SHOWN.




JACKSONVILLE DISTRICT, CORPS OF ENGINEERS
JACKSONVILLE, FLORIDA

CHECKED BY: DATED: MARCH 2013

CUT-13 STATION 3+00 TO 5+00 GENERAL REEVALUATION REPORT II - ENGINEERING APPENDIX

NOTE: SHORELINE FALLS OUTSIDE LIMITS OF SECTION ON SECTIONS WHERE APPROXIMATE

SHORELINE SYMBOL IS NOT SHOWN.



JACKSONVILLE, FLORIDA


DATED:

MARCH 2013

CUT-13 STATION 6+00 TO 8+00 GENERAL REEVALUATION REPORT II - ENGINEERING APPENDIX

SECTION ON SECTIONS WHERE APPROXIMATE

SHORELINE SYMBOL IS NOT SHOWN.




JACKSONVILLE, FLORIDA

DATED: MARCH 2013

CUT-13 STATION 9+00 TO 11+00 GENERAL REEVALUATION REPORT II - ENGINEERING APPENDIX

SECTION ON SECTIONS WHERE APPROXIMATE

SHORELINE SYMBOL IS NOT SHOWN.




JACKSONVILLE DISTRICT, CORPS OF ENGINEERS
JACKSONVILLE, FLORIDA

DATED:

MARCH 2013

CUT-13 STATION 12+00 TO 14+00 GENERAL REEVALUATION REPORT II - ENGINEERING APPENDIX

SECTION ON SECTIONS WHERE APPROXIMATE




JACKSONVILLE DISTRICT, CORPS OF ENGINEERS
JACKSONVILLE, FLORIDA

DATED:

MARCH 2013

CUT-13 STATION 15+00 TO 17+00 GENERAL REEVALUATION REPORT II - ENGINEERING APPENDIX SECTION ON SECTIONS WHERE APPROXIMATE




JACKSONVILLE, FLORIDA

DATED: MARCH 2013


CUT-13 STATION 18+00 TO CUT-14/15 STATION 2+00 GENERAL REEVALUATION REPORT II - ENGINEERING APPENDIX

SECTION ON SECTIONS WHERE APPROXIMATE



DATED: MARCH 2013

CUT-14/15 STATION 3+00 TO 5+00 GENERAL REEVALUATION REPORT II - ENGINEERING APPENDIX





JACKSONVILLE DISTRICT, CORPS OF ENGINEERS
JACKSONVILLE, FLORIDA

DATED:

MARCH 2013

CUT-14/15 STATION 6+00 TO 8+00 GENERAL REEVALUATION REPORT II - ENGINEERING APPENDIX NOTE: SHORELINE FALLS OUTSIDE LIMITS OF

SECTION ON SECTIONS WHERE APPROXIMATE

SHORELINE SYMBOL IS NOT SHOWN.